

## Replacement Chamber Kits

MANUFACTURER MODEL	LYNN ITEM #	MANUFACTURER MODEL	LYNN ITEM #	MANUFACTURER MODEL	LYNN ITEM #
<b>AMERICAN STANDARD</b>		<b>BURNHAM (continued)</b>		<b>DUNKIRK</b>	
A-3 SERIES—All models--	<a href="#">1065</a>	<b>MEGASTEAM</b>		<b>EMPIRE WATER</b>	
VP(T) - All models -----	<a href="#">1064</a>	MST228, MST396, MST513 --	<a href="#">1177</a>	OEM #14614015 & 14619003 ---	<a href="#">1105</a>
V-3 - All models -----	<a href="#">1065</a>	MST629 -----	<a href="#">1178</a>	3E.60 (C), 3E.75 (C),	
<b>BARD OIL FURNACES</b>		<b>RS SERIES</b>		3E1.00 (C), 4E.90 (C),	
OEM #7090-005 -----	<a href="#">1131</a>	RS-109, RS-110, RS-111 ---	<a href="#">1107</a>	4E1.25 (C), 4E1.50 (C)	
D36C, D48C, D60C, F81, F86CF,		RS-112, RS-113, RS-114		5E1.20 (C), 5E1.75 (C),	
F86H, F97, F100CF, FC085,		<b>RSM SERIES</b>		5E2.00 (C)	
FH085, FH110, FLF085, FLF110,		RSM-96, RSM-126 -----	<a href="#">1107</a>	<b>EMPIRE II WATER</b>	
FLR085, FLR110		<b>RSA SERIES</b>		OEM #14619003 & 14614014 ---	<a href="#">1132</a>
<b>BRYANT -PREFERRED SERIES</b>		RSA-85, 110, 125 & 135 --	<a href="#">1173</a>	3EW.65, 3EW.75, 3EW1.00,	
<b>BW4 &amp; BW5 BOILERS</b>		<b>CARRIER</b>		4EW.90, 4EW1.25,	
NO Swing-Out Door-----	<a href="#">1105</a>	<b>PERFORMANCE 86, BW4 &amp; BW5</b>		4EW1.50, 5EW1.20,	
With Swing-Out Door -----	<a href="#">1132</a>	NO Swing-Out Door-----	<a href="#">1105</a>	5EW1.75, 5EW2.00	
<b>BURNHAM</b>		With Swing-Out Door -----	<a href="#">1132</a>	<b>EMPIRE STEAM II</b>	
<b>C3 &amp; C4 SERIES</b> -----	<a href="#">1074</a>	<b>COLUMBIA</b>		ESB or ESC0365, 3100 -----	<a href="#">1096</a>
<b>LE &amp; LEDV- All Models</b>		<b>CSF SERIES</b>		4100, 4125, 4150,	
LE1, LE2, LE1-L, LE1-H, DV	<a href="#">1167</a>	CSF-365, CSF-3100, -----	<a href="#">1095</a>	5175, 5200, 6225 & 7275	
OEM 8203301, 8203302,		CSF-4125, CSF-4150,		<b>EV SERIES</b>	
8203303		CSF-5175, CSF-5200		DPFO-3 -----	<a href="#">1075</a>
<b>3W &amp; 4W SERIES</b> -----	<a href="#">1074</a>	CSF-6225, CSF-7280		DPFO-3T, 4, 4T, 5, 5T ----	<a href="#">1073</a>
<b>V1 SERIES</b>		<b>CSFH-3 &amp; CSFE</b>		DPFO-6T,7, 8T &9	
OEM 8202211, -----	<a href="#">1064</a>	CSF(H or E)-365, 3100, ---	<a href="#">1096</a>	<b>ELECTRIC FURNACE-MAN</b>	
8202701 & 8202210		3125, 4100, 4125, 4150,		<b>OBT-5 SERIES</b>	
V13, V14, V15, V16, V17,		5125, 5175, 5200, 6150, 7275		OBT75C5, OBT100C5, ---	<a href="#">1067</a>
V18, V172, V196		<b>LV &amp; LVD SERIES</b>		OBT125C5, OBT150C5,	
<b>V3 SERIES</b>		OEM #337801, #337816, ----	<a href="#">1172</a>	OBT175C5, OBT200C5	
OEM #8202307 & 8202301--	<a href="#">1065</a>	#337803, 337804		OBT250C5, OBT275C5,	
V33, V34, V35 & V36		<b>EMERALD</b>		OBT300C5	
<b>V7 SERIES</b>		OEM #337345 -----	<a href="#">1175</a>	<b>HYDROTHERM</b>	
V72, V73, V713, V74, V714,		EM-85(E), 100(E), 110(E) & 125(E)		<b>OR SERIES</b>	
V75, V76, V77, V78		<b>CROWN</b>		OR-175, 210 & 280 -----	<a href="#">1077</a>
NO Swing-Out Door-----	<a href="#">1066</a>	<b>BAHAMA</b>		OR-330 & 385 -----	<a href="#">1078</a>
OEM #8202701 & #8202702		<b>OEM #14614015 &amp; 14619003 ---</b>		<b>MULTITEMP</b>	
With Swing-Out Door ----	<a href="#">1074</a>	BD-74, BD-91, BD-111, BD-120, BD-147,		MO/G-420, 560, 660 -----	<a href="#">1077</a>
OEM #8202701 & #82027021		BD-151, BD-178, BD-211, BD-238		840, 990, 1320	
<b>V8 V8H SERIES</b>		<b>BAHAMA SWING-OUT</b>		MO/G-770, 1155, 1320 ---	<a href="#">1078</a>
OEM# 8202701 & #82028004		OEM #14619003 & 14614014 ---		1540, 1925, 2310, 2695, 3080,	
V82, V83, V84, V85, -----	<a href="#">1129</a>	BDS-80, BDS-92, BDS-111, BDS-119, BDS-		3465, 3850, 4235, 4620, 5005,	
V86, V8H2, V8H3, V8H4,		147, BDS-150 BDS-178, BDS-209, BDS-236		5390, 5775, 6160, 6545, 6930A	
V8H5, V8H6		<b>FREEMPORT II</b>		<b>PB SERIES</b>	
V87, V88, V89 -----	<a href="#">1130</a>	FWZ060, 080, 100, 130---		PB-105, PB-120, PB-150, PB-180,	
V8H7, V8H8, V8H9		FSZ080, 100, 130		PB-200, PB-235, PB-245, PB-295	
<b>MPO</b>		FWZ160 & FSZ160-----		NO Swing-Out Door-----	<a href="#">1104</a>
MPO-IQ84 & IQ115-----	<a href="#">1177</a>	<b>TOBAGO &amp; KINGSTON</b>		With Swing-Out Door -----	<a href="#">1153</a>
MPO-IQ147 & IQ189		TWZ & KSZ - ALL SIZES ----			
MPO-IQ231 -----	<a href="#">1178</a>			<b>KERR</b>	
				<b>F70, F75 &amp; F100</b>	
				See Valliant Listing	

MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #
<b>LAARS</b>		<b>NEW YORKER (continued)</b>		<b>OLSEN/AIRCO FURNACES</b>	
<b>NEWPORT</b>		<b>FR SERIES</b>		OEM #9200C, #28562 ----- <a href="#">1158</a>	
OEM #51-088 ----- <a href="#">1174</a>		<b>COMBUSTION CHAMBER KITS</b>		& #8823B1 Firepot	
NP-85, 100 & 110		FR-HGS 98 & 122, ----- <a href="#">1161</a>		BCL-120(S)(ST), 145(S)(ST)	
<b>LENNOX</b>		FR-HGSII 98 & 122		BFL-120, 120T, 145 & 145T	
<b>CONSERVATOR SERIES</b>		OEM #62072001		HTL-100B/C & WTL-100	
COWB-3, 4&5 ----- <a href="#">1105</a>		FR-147, 173, 205, 232----- <a href="#">1162</a>		<b>ONEIDA ROYAL</b>	
COWB2-3, 4 & 5 ----- <a href="#">1132</a>		OEM #62072002		L-HO-145DA4 ----- <a href="#">1158</a>	
<b>METROMATIC</b>		<b>FLUE BOX KITS</b>		L-HO-145DA5	
LB/HBSU 84, 100, 120 ----- <a href="#">1187</a>		FR-HGS 98 & 122 ----- <a href="#">1164</a>		<b>PEERLESS</b>	
LB/HBSU 140, 200, 275----- <a href="#">1188</a>		OEM #62072006		<b>EC/ECT - All models</b>	
<b>MILLER/NORDYNE</b>		FR-147 & 173----- <a href="#">1166</a>		OEM #50661, #50768, --- <a href="#">1093</a>	
<b>MOBILE HOME</b>		OEM #62072008		#50765	
CMF, MOC & MGC ----- <a href="#">1029</a>		<b>NY SERIES</b>		EC-03, EC-04, EC-05, EC-06	
OEM #901818		NY-124-1, NY-151-1 ----- <a href="#">1106</a>		ECT-03, ECT-04, ECT-05,	
CMF2 ----- <a href="#">1141</a>		NY-168-1, NY-194-1, NY-224-1		ECT-06, CC4028, EC3002	
<b>M1/M5 SERIES</b>		<b>AP SERIES</b>		<b>JO/JOT - All models</b>	
OEM #903423----- <a href="#">1141</a>		AP-490, AP-510, ----- <a href="#">1103</a>		OEM #50661, #CC-3025-- <a href="#">1067</a>	
Fits all M1S, M1B & M5S		AP-590 AP-670, AP-690,		JO-3, JO-35, JO-4, JO-45,	
<b>MEMCO</b>		AP-790, APD-96		JO-5, JO-6, JO-75, JOT-3, JOT-35,	
<b>SST SERIES</b>		AP-780, AP-840, ----- <a href="#">1106</a>		JOT-4, JOT-45, JOT-5, JOT-6,	
NO Swing-Out Door- ----- <a href="#">1105</a>		AP-890, AP-1160		JOT-75, TWO75, TW100, TW125,	
With Swing-Out Door ----- <a href="#">1132</a>		<b>AP-U SERIES</b>		TW150, TW175, TW200, TW250,	
<b>CST-PLUS</b>		AP-490U, AP-590U, ----- <a href="#">1173</a>		TW275, TW300	
CSTO-3 ----- <a href="#">1075</a>		AP-690U, AP-790U		<b>SC/SCT</b>	
CSTO-3T,4,4T,5&5T ----- <a href="#">1073</a>		<b>S or KD SERIES</b>		OEM #50768 & #50765 --- <a href="#">1179</a>	
CSTO-6T, 7, 8T, 9		97-AP, 107-AP, 118-AP ----- <a href="#">1103</a>		SC-05, SC-06, SC-07, SC-08,	
<b>NEW YORKER BOILER</b>		131-AP, 154-AP ----- <a href="#">1106</a>		SC-09, SC-10, SCT-05, SCT-06,	
OEM #C11750 ----- <a href="#">1103</a>		114-AP, 122-AP, 132-AP 142-AP,		SCT-07, SCT-08, SCT-09, SCT-10	
OEM #8203006 ----- <a href="#">1173</a>		165-AP, 176-AP, 193-AP, 203-AP,		<b>WB, WV &amp; WB/WV</b>	
OEM #PC12000 ----- <a href="#">1106</a>		222-AP, 230-AP, 500, 580, 660,		OEM #50795 & 50794 ----- <a href="#">1071</a>	
<b>CI-HGS SERIES</b>		720, 840, 990		Fits WB, WV, WV-DV & WBV	
CI-HGS-74B & 101B----- <a href="#">1177</a>		<b>PH SERIES</b>		WB-03, WB-04, WB-05	
CI-HGS-129B & 167B		PH-132, PH-142, PH-154 ----- <a href="#">1106</a>		<b>PENNCO</b>	
<b>CLASSIC SERIES</b>		PH-165, PH-176, PH-203 ,PH-222,		<b>KEYSTONE WATER</b>	
CLW-3, 4, 5 & 6 ----- <a href="#">1134</a>		PH-230, CPH-165, CPH-176		3K.60(C), 3K.75(C), ----- <a href="#">1105</a>	
CL-3S, 4S, 5S, 6S& 7S		<b>OS SERIES</b>		3K.100(C), 4K.90(C), 4K1.25(C),	
OEM #121900 & #8202701		OS-123-1 & 140-1----- <a href="#">1103</a>		4K1.50(C), 5K1.20(C), 5K1.75(C),	
CL3-091, 105 & 140 ----- <a href="#">1155</a>		OS-101-1, 113, 120-1 ----- <a href="#">1106</a>		5K2.00(C)	
CL4-126, 175 & 210		122, 132, 142, 143-1,		<b>KSC STEAM</b>	
CL5-168, 245 & 280		161-1, 165, 170-1, 191-1, 222		KSC0365S, KSC3100S ----- <a href="#">1096</a>	
OEM #270021 & #270025		<b>UCG SERIES</b>		KSC4100S, KSC4125S	
NO Swing-Out Door- ----- <a href="#">1134</a>		UGC-100----- <a href="#">1103</a>		KSC4150S, KSC5175S	
With Swing-Out Door & ----- <a href="#">1155</a>		UGC-100, 125, 125-1 ----- <a href="#">1106</a>		KSC5200S, KSC6225S, KSC7275S	
Observation Hole on Right Side		140,150-1, 154-1, 164,		<b>PUREPRO</b>	
With Swing-Out Door & ----- <a href="#">1074</a>		170, 189-1		<b>ADVANTAGE</b>	
Observation Hole on Left Side		<b>WH SERIES</b>		AO(T)-3, 4 & 5 ----- <a href="#">1155</a>	
<b>MICROTEK</b>		WH-132, WH-142, ----- <a href="#">1106</a>		<b>REZNOR</b>	
3 & 3DV-All Models ----- <a href="#">1167</a>		WH-154, WH-165, WH-176		<b>RA &amp; RAD Waste Oil Heaters</b>	
OEM 8203301, 8203302,		<b>OLSEN BOILERS</b>		110, 140,150, 235, 250, 350 <a href="#">1189</a>	
8203303		<b>OSFH</b> ----- <a href="#">1096</a>		<b>SEARS</b>	
		OSFH-365, 3100, 3125,		<b>KENMORE 44</b>	
		4100, 4125, 4150, 5125,		94413(C), 94414(C), ----- <a href="#">1105</a>	
		5175, 5200, 6150, 6225,		94415(C), 94423(C), 94424(C),	
		& 7275		94425(C) 94433(C), 94434(C),	
				94435(C)	

MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #
<b>SLANT/FIN</b> <b>XL-2000</b> XL-20, XL-30, XL-40, XL-50 --- <a href="#">1088</a>		<b>THERMO-DYNAMICS</b> <b>LM &amp; LMD SERIES</b> OEM #337801, 337816, ----- <a href="#">1172</a> 337803, 337804		<b>VAILLANT</b> <b>F70 &amp; F75 SERIES</b> OEM #2015-114 ----- <a href="#">1117</a> F70/75-40, 45, 50 & 55	
<b>LIBERTY</b> —All Models P, PT, PPT, PZ, ----- <a href="#">1087</a> PZT, L-20, L-20BK, L-30H, L-30HF, L-30, L-40H, L-40, L-50H, L-50HF, L-50, L-60, L-70, L-70C, L-70P, L-70PT, L-70PPT, L-70WKD, L-70WU		<b>S SERIES</b> OEM #337350 ----- <a href="#">1176</a> S or STR-85, 100, 110, 125, 135 & 150		<b>F100 SERIES</b> F100-30, 40, 50 & 60 ----- <a href="#">1119</a>	
<b>LIBERTY II</b> —All Models LD-20, LD-30H, ----- <a href="#">1127</a> LD-30, LD-40H, LD-40, LD-50H, LD-50, LD-60, LD-70		<b>THERMOFLO - BOILERS</b> <b>OWB, OWT- ALL</b> ----- <a href="#">1126</a> <b>OSB, OST- ALL</b> ----- <a href="#">1126</a>		<b>WEIL MCLAIN</b> <b>65 SERIES</b> 465, 565, 665, 765, 865 - <a href="#">1101</a> <b>66 SERIES</b> OEM #386-500-085 ----- <a href="#">1060</a> 266, 366, 466, 566, 666, 766	
<b>INTREPID</b> —All Models TR-20, TR-30, TR-40, ----- <a href="#">1127</a> TR-50, TR-60, TR-70,		<b>ULTIMATE ENGINEERING</b> <b>PFO SERIES</b> PFO-3 ----- <a href="#">1075</a> PFO-3T, 4, 4T, 5, 5T ----- <a href="#">1073</a> 6T, 7, 8T, 9		<b>68 / 68V SERIES</b> OEM #386-500-085 ----- <a href="#">1060</a> 268, 368, 468, 568 668, 768, 868, 968	
<b>CARAVAN</b> —All Models 600-2-5, 750-2-6, ----- <a href="#">1127</a> 850-2-7, 900-3-5, 1100-3-6 1300-3-7, 1700-4-7, 2100-5-7, 2500-6-7, 2900-7-7, 3400-8-7		<b>UTICA RADIATOR</b> <b>STARFIRE II</b> OEM #5611508, RD160A ---- <a href="#">1095</a> SF-365, SF-3100, SF-4125 SF-4150, SF-5175, SF-5200 SF-6225, SF-7275		<b>GO SERIES (Gold)</b> OEM #386-700-355 All WTGO, WGO, SGO 2 Thru 8 Section----- <a href="#">1072</a> WGO-2, WGO-3, WGO-4, WGO-5, WGO-6, WGO-7, WGO-8 9 SECTION ONLY----- <a href="#">1148</a> WGO-9	
<b>H.B. SMITH</b> <b>BB14 &amp; OB14</b> -All Models OEM #60462 ----- <a href="#">1159</a>		<b>STARFIRE III &amp; IV</b> OEM #2552901, ----- <a href="#">1096</a> 2553303, 5611508 SF(H or E)365, 3085, 3090, 3100, 3125, 4100, 4125, 4145, 4150, 5125, 5160, 5175, 5185, 5200, 6150, 6175, 6210, 6225, 7275		<b>76 SERIES</b> 476, 576R, 576, 676 ----- <a href="#">1120</a> 776, 876, 976	
<b>FD-12</b> All Models ----- 1068		<b>SW SERIES</b> SW3, SW4, SW5 ----- <a href="#">1096</a>		<b>78 &amp; 80 SERIES</b> 4" Burner Opening----- <a href="#">1121</a> 6" Burner Opening----- <a href="#">1122</a>	
<b>SERIES 8</b> NO Swing-Out Door- ----- <a href="#">1104</a> OEM# 69406, 69356 8-W-3, 8-W-4, 8-W-5, 8-W-6 8-S-3, 8-S-4, 8-S-5, 8-S-6 With Swing-Out Door ----- <a href="#">1153</a> OEM# 69406, 61137, 61138, 61136, & 60023		<b>CONSTELLATION</b> SFM6225W, 7275W----- <a href="#">1096</a> 24150W, 25175W, 25200W, 26225W, 27275W, 36225W, 37275W, 47275W, 57275W, 67275W, 77275W, 87275W		<b>WILLIAMSON - BOILERS</b> <b>OWB, OWT - ALL</b> ----- <a href="#">1126</a> <b>OSB, OST - ALL</b> ----- <a href="#">1126</a>	
<b>SERIES 8HE</b> 8HE-3, 8HE-4, 8HE-5 ----- <a href="#">1071</a>				<b>Retired Kits No Longer Available:</b> 1004, 1017, 1061, 1080, 1081, 1082, 1083, 1086, 1156, 1163, 1165, 1168, 1169, 1170, 1171, 1180, 1181, 1182, 1183, 1184	
<b>TRIANCO</b> <b>DBC</b> OEM #51-088 ----- <a href="#">1174</a> DBC-85, 100,110 & 115					

Document Updated 5/2022



**Application, Installation and Use Warning:**

In applications including; boilers, furnaces, wood stoves, wood inserts, fireplaces, heating devices, and other appliances, parts must be used consistently with original equipment manufacturers specifications, design, function and operation.

Improper installation or use of this product could result in a fire, smoke inhalation or carbon monoxide poisoning. Products should be installed by a licensed and certified technician in compliance with all national, state and local codes. Products should be inspected annually by a licensed and certified technician for wear, brittleness, cracking or crumbling, and replaced as necessary. Lynn Manufacturing, Inc. recommends installers certified by NFI, CSIA or NORA.

Never work on a piece of equipment or touch the fibrous product when it is hot, as the product may show no visible signs of heat from glowing or smoking.

Lynn Manufacturing, Inc offers hundreds of products with many applications. Determining whether the product is a fit for the particular purpose and suitable for an application is the sole responsibility of the purchaser/installer.

In no event shall Lynn Manufacturing, Inc be liable for any damages to property or life arising from or connected with the use of this product.